






NOTES AND SPECIFICATIONS:

- 1. use Plices to connect all wires
- 2. Compartment 1 is nearest to front of truck



**OPW FLUID TRANSFER GROUP EUROPE BV**  
 A TRIVER RESOURCE COMPANY, MEIJWENNER, THE NETHERLANDS

**OPW CIVACON**

© Copyright 2011. This drawing is the exclusive property of OPW Fluid Transfer Group Europe BV. It is submitted on the condition that the recipient will not reproduce, copy, distribute, or otherwise use this drawing without the written consent of OPW Fluid Transfer Group Europe BV.

TITLE	Swire TOP SENSOR WIRING DIAGRAM TO 10 PIN SOCKET CONFORM NEN-EN13922
DRAWN:	LAK
DATE:	2-MRT-05
DRAWING NO.	DS00143
SIZE	A2
SHEET	1
SCALE	1:1
PROJECTION:	B
DIMENSIONS:	mm
ECO DATE:	25x2-10
ORIGIN:	
TABLE:	
REVISIONS:	